JON R O'HARE 17479 7TH AVE SW NORMANDY PARK, WA 98166

Re: Project #6698208-DM-004

Correction Notice #2

Review Type GEO SOILS Project Address 801 3RD AVE

SEATTLE, WA 98104

Contact Email JON@PERMITCNW.COM

SDCI Reviewer Pao Huang **Reviewer Phone** (206) 684-5825

Reviewer Email pao.huang@seattle.gov

Owner D LLC

Date May 27, 2021 **Contact Phone** (425) 301-9541

Address Seattle Department of Construction and

Inspections 700 Fifth Ave Suite 2000 PO Box 34019

Seattle, WA 98124-4019

Description of Work:

Revision: Install temporary rubble bracing, per plan.

Reference:

March 12, 2021 "Geotechnical Recommendations for Rubble Berm Support of Basement Wall ", by Hart Crowser (File No. 19567-01)

Document Reviewed:

Plan Set Cycle2 uploaded on 5/5/2021 (1.61 MB)

Applicant Instructions

You will not be able to upload corrected plans until all reviews are completed and the project's review status is "Corrections Required".

*** Respond by providing a written response to each correction AND identify changes to drawings since initial review. ***

Drawings shall be **legible**, with sheets **oriented correctly**, on an appropriate **sheet size**, with all revisions/changes **clouded or circled**, with **no missing sheets**, and uploaded in a **single PDF file**.

Link for detailed steps: "How to Respond to a Correction Notice". If the 3-step process outlined in this document is not followed, your response could be **rejected**, permit issuance could be **delayed**, and **penalty fees** could be assessed.

Codes Reviewed

This project has been reviewed for conformance with one or more of the following codes: 2015 Seattle Building Code (SBC); 2015 Seattle Residential Code (SRC); 2015 Seattle Existing Building Code (SEBC); 2015 Seattle Energy Code (SEC); Grading Code; Environmentally Critical Areas Regulations (ECA).

Project #6698208-DM-004, Correction Notice #2

This project has been reviewed for conformance with one or more of the following codes: 2018 Seattle Building Code (SBC); 2018 Seattle Residential Code (SRC); 2018 Seattle Existing Building Code (SEBC); 2018 Seattle Energy Code (SEC); Grading Code; Environmentally Critical Areas Regulations (ECA).

Corrections

1. [Resolved]

2. Revised and Repeated

The monitoring program recommended by the geotechnical engineer should be included in the plan.

monitoring plan has been added to plans

- 3. [Resolved] SMC 22.170.190 A. Plan review/minimal risk letter
- 4. [Resolved] SMC 25.09.080 D and 22.170.080 A.1. Liability insurance
- 5. [Resolved] SMC 22.170.130. Geotechnical Special Inspections

	Addition to Previous Schedule	
SDCI Geotechnical In	ispections schedule	
Project Number 6698208-DM-00	04 Date 5/	/27/2021 2:38 PM
Project Address 801 3RD AVE SEATTLE, WA 9	98104 SDCI Plan Pao Hua Examiner	ang
Architect	Architect Phone	
Engineer	Engineer Phone	
	amed below has been engaged to perform the special inspection It is the responsibility of the owner or the owner's designee to inspections listed below are required.	
hereby certify that the geotechnical engineer na elow as required by the Seattle Building Code. I	It is the responsibility of the owner or the owner's designee to anspections listed below are required.	
hereby certify that the geotechnical engineer na selow as required by the Seattle Building Code. Inspection agency in a timely manner when the in	It is the responsibility of the owner or the owner's designee to anspections listed below are required.	
hereby certify that the geotechnical engineer na selow as required by the Seattle Building Code. It is pection agency in a timely manner when the insignature Title	It is the responsibility of the owner or the owner's designee to an appections listed below are required. Date Phone	notify the
hereby certify that the geotechnical engineer na selow as required by the Seattle Building Code. Inspection agency in a timely manner when the insignature HART CROWSER INC	It is the responsibility of the owner or the owner's designee to a spections listed below are required. Date	notify the
hereby certify that the geotechnical engineer na selow as required by the Seattle Building Code. It is pection agency in a timely manner when the insignature HART CROWSER INC Geotechnical Engineering Firm Name	It is the responsibility of the owner or the owner's designee to a spections listed below are required. Date	notify the
hereby certify that the geotechnical engineer na selow as required by the Seattle Building Code. It is necessary in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency in a timely manner when the inspection agency is a second agency is a second agency in a second agency is a second agency in a timely manner when the inspection agency is a second agency	It is the responsibility of the owner or the owner's designee to a spections listed below are required. Date	notify the

Project #6698208-DM-004, Correction Notice #2